

# Los Robles Regional Medical Center

As you are probably aware, we've been experiencing problems in our electrical system. The problems were in the Clinical Lab and Outpatient Clinic. In these areas, when the emergency generators were being tested, the computer located in the Clinical Lab and the Farrington Addressograph in the Outpatient Clinic would malfunction. The computer would lose its memory circuit and the Farrinton Addressograph would run constantly. Since the installation of the Wire-in Supression Device, six weeks ago, we have had no problems.