



1946 - 1996 Celebrating Over 50 Years of Excellence

10100 Dixie Highway
Clarkston, Michigan 48348

In the past, we have had customers experiencing problems with their electronic equipment failing. After several service calls to troubleshoot, we found power surges from the station's equipment and from the power company had caused the electronic components to fail. One site, in the Detroit area, had been complaining about their cooler and their POS system going down. We installed a recorder on the service coming into the building and found the voltage would range from 90 volts to 130 volts throughout the day. Since installing the TVSS, we have had no reports of any further problems, even through electrical storms.