



LONG BEACH HOSPITAL
1725 PACIFIC AVE., LONG BEACH, CA 90813 (213) 599-3551

As you well know, our ICU equipment was persistently being "Knocked Out" by a heavy voltage surge, generated by the weekly "Switchover" to emergency power. We had been living with the problem for quite some time and had to resort to unplugging the equipment, prior to the weekly test.

With the installation of your two suppressors, one at the main entry panel and the other at the distribution panel feeding the ICU equipment, the problem has been eliminated.